

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-022016**Date Inspected:** 28-Feb-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Lv Li Qing**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance(QA) Inspector Mr.Shrikant Utekar was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. The QA Inspector observed and/or found the following:

BAY # 14

ULTRASONIC TESTING

ZPMC NWIT No: 08419

This QA Inspector performed Ultrasonic Testing (UT) of approximately 10% of the length previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an (UT) report on this date. The members are identified as vertical shear plate. The weld designations are as follows:

SEG3019BB-037

This QA Inspector randomly observed the following work in progress.

OBG 14EAST

This QA Inspector observed installation and erection of EP3027E was in progress in OBG lift 14 east.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 050232 performing the Shielded Metal Arc Welding process on weld 011 located at PCMK SEG3019Z. ZPMC QC Mr. Zhong Guo Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-345-SMAW-2G (2F)-Fcm-Repair-1. Critical weld repair report identified as B-CWR2755.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 069894 performing the Shielded Metal Arc Welding process on weld 012 located at PCMK SEG3019Z. ZPMC QC Mr. Zhong Guo Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-345-SMAW-2G (2F)-Fcm-Repair-1. Critical weld repair report identified as B-CWR2755.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 067665 performing the Shielded Metal Arc Welding process on weld 104 located at PCMK SEG3019AB. ZPMC QC Mr. Zhong Guo Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-P-2114-Fcm-1.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 066439 performing the Flux Cored Arc Welding process on weld 228 located at PCMK SEG3019K. ZPMC QC Mr. Zhong Guo Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-T-2233-ESAB.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 067079 performing the Flux Cored Arc Welding process on weld 248 located at PCMK SEG3019J. ZPMC QC Mr. Zhong Guo Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-T-2233-ESAB.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 066733 performing the Flux Cored Arc Welding process on weld 178 located at PCMK SEG3019H. ZPMC QC Mr. Zhong Guo Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-T-2233-ESAB.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 068917 performing the Shielded Metal Arc Welding process on weld 018 located at PCMK FB3287-001. ZPMC QC Mr. Zhong Guo Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-P-2114-Fcm-1.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 067079 performing the Shielded Metal Arc Welding process on weld 135 located at PCMK SEG3019BB. ZPMC QC Mr. Zhong Guo Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-345-SAMW-3G (3F)-Fcm-Repair-1. Weld repair report identified as B-WR20270.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)



Summary of Conversations:

No significant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, +(86) 1500 042 2372, who represents the Office of Structural Materials for your project.

Inspected By:	Utekar,Shrikant	Quality Assurance Inspector
Reviewed By:	Patterson,Rodney	QA Reviewer
